

User advice for Nitto 51A:

- ☐ Keep rolls at temperature
 - > Don't keep in a cold warehouse or van
 - > Recommend worker to keep the roll in his pocket until application
- ☐ Always cut by knife (don't tear by hand)
- ☐ To prevent gapping on the side:
 - > Lamination
 - > Open the part
 - > Relaminate by stretch

A COLD APPLIED JOINT CLOSURE SYSTEM THAT CAN BE USED ON ALL NON-PRESSURISED CABLES.













Innovation for Customers